

Intertek Testing Services Shanghai Building No.86, 1198 Qinzhou Road (North), Caohejing Development Zone, Shanghai 200233, China Tel:86 21 6127 8200 Fax:86 21 6495 6263

Test Verification of Conformity

On the basis of the referenced test report(s), sample(s) of the below product have been found to comply with the harmonized standards and Directives listed on this verification at the time the tests were carried out. Other standards and Directives may be relevant to the product.

Once all product relevant mark directives are verified in compliance, the manufacturer may indicate compliance by signing a Declaration of Conformity themselves and applying the mark to product identical to the test sample(s) if the product complies with all relevant CE mark Directives requirements.

Applicant Name & Address

Hangzhou Hanlight Electrical Co., Ltd.

No.1228 West Park Road, Fuyang City, Zhejiang Province.

P.R. China.

Manufacturing site Name &

Address

Same as applicant

Product(s) Tested

Flush-type switch for fixed installation

Ratings and principal

characteristics

250V~ 10AX

Model(s)

See annex

Brand name

Hanlight

Relevant Standard(s) /

Specification(s) / Directive(s)

EN 60669-1:1999 + A1:2002 + A2:2008 The Low Voltage Directive 2006/95/EC

Verification Issuing Office Name & :

Address

Intertek Testing Services Shanghai

Building No.86, 1198 Qinzhou Road (North), Shanghai

200233, China

Verification Number

141102009SHA-V1

Report Number(s)

141102009SHA-001

NOTE 1: This verification is part of the full test report(s) and should be read in conjunction with it.

This Verification is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Verification. Only the Client is authorized to copy or distribute this Verification. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results referenced from this Verification are relevant only to the sample tested. This Verification by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

CE

Oliver Wei Manager January 20, 2015



Annex to Test Verification of Conformity

This is an Annex to Test Verification of Conformity with Verification Number(s): 141102009SHA-V1.The issuing office is Intertek Testing Services Shanghai (Address: Building No.86, 1198 Qinzhou Road (North), Caohejing Development Zone, Shanghai 200233, China)

Model list:

FC3011, MC3011, EF-P3011, EP-P3011, EC-P3011, FF-P3011, FT-P3011, DE-P3011, RA-P3011, MC-P3011, BH-P3011, BV-P3011, BC-P3011, BE-P3011, FF-U3011, FT-U3011, DE-U3011, RA-U3011, BH-U3011, BV-U3011, BC-U3011, BE-U3011

FC3012, MC3012, EF-P3012, EP-P3012, EC-P3012, FF-P3012, FT-P3012, DE-P3012, RA-P3012, MC-P3012, BH-P3012, BV-P3012, BC-P3012, BE-P3012, FF-U3012, FT-U3012, DE-U3012, RA-U3012, BH-U3012, BV-U3012, BC-U3012, BE-U3012

FC3021, MC3021, EF-P3021, EP-P3021, EC-P3021, FF-P3021, FT-P3021, DE-P3021, RA-P3021, MC-P3021, BH-P3021, BV-P3021, BC-P3021, BE-P3021, FF-U3021, FT-U3021, DE-U3021, RA-U3021, BH-U3021, BV-U3021, BC-U3021, BE-U3021

FC3022, MC3022, EF-P3022, EP-P3022, EC-P3022, FF-P3022, FT-P3022, DE-P3022, RA-P3022, MC-P3022, BH-P3022, BV-P3022, BC-P3022, BE-P3022, FF-U3022, FT-U3022, DE-U3022, RA-U3022, BH-U3022, BV-U3022, BC-U3022, BE-U3022

FC3031, MC3031, EF-P3031, EP-P3031, EC-P3031, FF-P3031, FT-P3031, DE-P3031, RA-P3031, MC-P3031, BH-P3031, BV-P3031, BC-P3031, BE-P3031, FF-U3031, FT-U3031, DE-U3031, RA-U3031, BH-U3031, BV-U3031, BC-U3031, BE-U3031

FC3032, MC3032, EF-P3032, EP-P3032, EC-P3032, FF-P3032, FT-P3032, DE-P3032, RA-P3032, MC-P3032, BH-P3032, BV-P3032, BC-P3032, BE-P3032, FF-U3032, FT-U3032, DE-U3032, RA-U3032, BH-U3032, BV-U3032, BC-U3032, BE-U3032

FC3041, MC3041, EF-P3041, EP-P3041, EC-P3041, FF-P3041, FT-P3041, DE-P3041, RA-P3041, MC-P3041, BH-P3041, BV-P3041, BC-P3041, BE-P3041, FF-U3041, FT-U3041, DE-U3041, RA-U3041, BH-U3041, BV-U3041, BC-U3041, BE-U3041

FC3042, MC3042, EF-P3042, EP-P3042, EC-P3042, FF-P3042, FT-P3042, DE-P3042, RA-P3042, MC-P3042, BH-P3042, BV-P3042, BC-P3042, BE-P3042, FF-U3042, FT-U3042, DE-U3042, RA-U3042, BH-U3042, BV-U3042, BC-U3042, BE-U3042

FC3061, MC3061, EF-P3061, EP-P3061, EC-P3061, FF-P3061, FT-P3061, DE-P3061, RA-P3061, MC-P3061, BH-P3061, BV-P3061, BC-P3061, BE-P3061, FF-U3061, FT-U3061, DE-U3061, RA-U3061, BH-U3061, BV-U3061, BC-U3061, BE-U3061

FC3062, MC3062, EF-P3062, EP-P3062, EC-P3062, FF-P3062, FT-P3062, DE-P3062, RA-P3062, MC-P3062, BH-P3062, BV-P3062, BC-P3062, BE-P3062, FF-U3062, FT-U3062, DE-U3062, RA-U3062, BH-U3062, BV-U3062, BC-U3062, BE-U3062

NOTE: This annex is part of the Test Verification of Conformity and should be read in conjunction with it.

This Verification is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this Verification. Only the Client is authorized to copy or distribute this Verification. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results referenced from this Verification are relevant only to the sample tested. This Verification by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Oliver Wei Manager January 20, 2015